







ATELIER PURCELL

HENLEY COUNTER & BAR STOOL



ATELIER PURCELL

HENLEY COUNTER & BAR STOOL



LEGS

Standard Wood

FOOT PLATE

Obsidian (SMO34)

COUNTER STOOL

COM Required: 3 m [2.5 yd]

COL Required: 5 m² [45 ft²]

BAR STOOL

COM Required: 3 m [2.5 yd]

COL Required: 5 m² [45 ft²]

U.S. NOTE ONLY:

ROLLING STOCK FRAME OPTIONS:
COMING SOON, PLEASE CONTACT
SHOWROOM FOR FUTURE DETAILS.









NOTES:

PLEASE CONFIRM DETAILS OF THIS TEAR SHEET WITH YOUR LOCAL SALES ASSOCIATE.

Purcell Design reserves the right to make technological and aesthetic improvements to its models, including changes to the sizes and materials, without notice. The technical drawings do not define the details of the product. The measurements shown are indicative and may undergo changes. In particular, the dimensions relevant to the padded parts are subject to usage tolerances over time caused by the normal adjustment of the padding. For specific information, please contact us directly or the dealer closest to you.

ATELIER PURCELL

HENLEY COUNTER & BAR STOOL WITH SWIVEL



ATELIER PURCELL

HENLEY COUNTER & BAR STOOL WITH SWIVEL



LEGS

Standard Wood

FOOT PLATE

Obsidian (SMO34)

COUNTER STOOL

COM Required: 3 m [2.5 yd]

COL Required: 5 m² [45 ft²]

BAR STOOL

COM Required: 3 m [2.5 yd]

COL Required: 5 m² [45 ft²]

ROLLING STOCK FRAME OPTIONS:
COMING SOON, PLEASE CONTACT
SHOWROOM FOR FUTHER DETAILS.



NOTES:

PLEASE CONFIRM DETAILS OF THIS TEAR SHEET WITH YOUR LOCAL SALES ASSOCIATE.

Purcell Design reserves the right to make technological and aesthetic improvements to its models, including changes to the sizes and materials, without notice. The technical drawings do not define the details of the product. The measurements shown are indicative and may undergo changes. In particular, the dimensions relevant to the padded parts are subject to usage tolerances over time caused by the normal adjustment of the padding. For specific information, please contact us directly or the dealer closest to you.